

表三：過水指數



清洗

棉質衣物



清洗

人造纖維衣物

過水指數



最低

1.17 (#2)

0.60 (#7)

最高

2.57 (#10)

1.05 (#8)

相差54%

相差43%



過水指數愈低，代表過水效果愈好。